


# SIMOREG 6RA70 DC MASTER

## Dimension Drawings



Converters for single-quadrant operation

3-ph. AC 400 V, 3000 A; 575 V, 2800 A; 690 V, 2600 A; 950 V, 2200 A




Fig. 9/13a

1) Minimum free space for air circulation; it is necessary to ensure that the cooling air intake is sufficient.