Selection and Ordering data Order No.).
SITRANS P300 pressure transmitters with PMC connection, single-chamber measuring housing, rating plate inscription in English						
with 4 20 mA / HART		F)	7 M F 8 1 2 3 -			
with PROFIBUS PA		F)	7	MF	81	24-
with FOUNDATION Fiel	dbus (FF)	F)	7	MF	81	25-
				ī,		-
Measuring cell filling	Measuring cell cleaning	1				
Silicone oil	normal		1			
Inert liquid	Cleanliness level 2 to DIN 25410		3			
Measuring span						
1 bar ¹⁾	(14.5 psi)			В		
4 bar 16 bar	(58 psi)			C D		
	(232 psi)			U		
Wetted parts materials Seal diaphragm	Measuring cell					
	5	-		_		
Hastelloy Process connection	Stainless steel			B		
 PMC Style Standard: Thread 1½" PMC Style Minibolt: front-flush 1" (minimum span: 500 mbar (7.25 psi), not available with 1-bar-measuring cell (Option B)) 				2 3		
 Non-wetted parts materials Stainless steel, deep-drawn and electrolytically polished 					4	
Version Standard versions 						1
Explosion protection • None			А			
 With ATEX, Type of proc - "Intrinsic safety (EEx Zone 20/21/22²⁾ Ex nA/nL (Zone 2)³⁾ With FM + CSA, Type of - "Intrinsic Safe (is)" (p 	ia)" of protection:					B C E
						IVI
socket)	.5 (polyamide) ⁴⁾ 1.5 (metal) 1.5 (stainless steel) but cable socket) less steel), without cable					A B C F G
 ½-14 NPT metal thread ½-14 NPT stainless stered 						H J

Selection and Ordering data		Order No.
SITRANS P300 pressure transmitters with PMC connection, single-chamber measuring housing, rating plate inscription in English		
with 4 20 mA / HART	F)	7 M F 8 1 2 3 -
with PROFIBUS PA	F)	7 M F 8 1 2 4 -
with FOUNDATION Fieldbus (FF)		7 M F 8 1 2 5 -
Display		
 Without display, with keys, closed covers 		1
 With display and keys, closed lid 		2
 With display and keys, lid with glass pane (setting on HART devices: mA, with PROFIBUS PA and FOUNDATION Fieldbus equipment: pressure unit) 		6
 With display (setting acc. to specifications, Order Code "Y21" or "Y22" required), lid with glass pane 		7

Power supply units see Chap. 8 "Supplementary Components".

- Included in delivery of the device: Brief instructions (Leporello) CD-ROM with detailed documentation

sealing ring

1) Only with "Standard" process connection"

- ²⁾ Not in conjunction with electrical connection option A.
- ³⁾ Only available together with electrical connection options B, C, F or G.
- ⁴⁾ Only together with HART electronics.

5) Without cable gland.

F) Subject to export regulations AL: 91999, ECCN: N.

Selection and Ordering data	Order code			
Further designs		HART	PA	FF
Add "-Z" to Order No. and specify Order Code.				
Cable socket for M12 plug				
metalStainless steel	A50 A51		√ √	√ √
Rating plate inscription				
(instead of English)				
• German	B10	1	1	1
FrenchSpanish	B12 B13	✓ ✓	1	√ √
Italian	B14	1	✓ ✓	¥
English rating plate	B21	✓	~	~
Pressure units in inH ₂ 0 and/or psi				
Quality inspection certificate (Five-step factory calibration) to IEC 60770-2	C11	~	~	✓
Inspection certificate Acc. to EN 10204-3.1	C12	*	~	~
Factory certificate Acc. to EN 10204-2.2	C14	•	~	~
Set output signal to upper limit of 22.0mA	D05	✓	✓	✓
Degree of protection IP68 (only for M20x1.5 and ½-14 NPT)	D12	~	~	✓
Mounting				
Weldable sockets for standard 1½" threaded connection	P01	✓	~	✓
 Weldable socket for minibolt connection 1" (incl. screw 5/16-18 UNC-2B and washer) 	P02	✓	~	✓
Additional data				
Please add "-Z" to Order No. and specify Order code(s) and plain text.				
Measuring range to be set	Y01	✓		
Specify in plain text (max. 5 characters): Y01: up to mbar, bar, kPa, MPa, psi				
Stainless steel tag plate (measuring point description)	Y15	~	~	~
Max. 16 char., specify in plain text: Y15:		,	,	,
Measuring point text Max. 27 char., specify in plain text: Y16:	Y16	•	V	•
Entry of HART address (TAG)	Y17	✓		
Max. 8 char., specify in plain text: Y17:				
Setting of pressure indication in	Y21	~	✓	~
pressure units Specify in plain text (standard setting: bar):				
Y21: mbar, bar, kPa, MPa, psi,				
Note: The following pressure units can be selected:				
bar, mbar, mm H_2O^{*}), in H_2O^{*}), ft H_2O^{*}), mmHG, inHG, psi, Pa, kPa, MPa, g/cm ² , kg/cm ² , Torr, ATM or %				
*) ref. temperature 20 °C				
Setting of pressure indication in non-pres- sure units ⁵⁾ Specify in plain text:	Y22 + Y01	•		
Y22: up to I, m ³ , m, USg,				
(specification of measuring range in pressure units "Y01" is essential, unit with max. 5 cha- racters)				
Preset bus address	Y25		~	
possible between 1 and 126				
Specify in plain text: Y25:				
Only "Y01" and "Y21" can be factory preset				

Only "Y01" and "Y21" can be factory preset