

Accessories

Order No.

for MAG 1100 sensor**Pipe connection ½" external thread**

For DN 2 ... 10 (1/12" ... 3/8") sensor,
material: SS 316
2 pipe connections, 2 EPDM gaskets,
12 pcs M4 x 12 screws

- ½" G, ISO 7-1 tapered thread, SS 316
- ½" NPT thread, SS 316

- ◆ **FDK-083G0080**
- ◆ **FDK-083G4330**

For DN 2 ... 10 (1/12" ... 3/8") sensor,
material: Hastelloy C
2 pipe connections, 2 PTFE gaskets,
12 pcs M4 x 14 screws

- ½" G, ISO 7-1 tapered thread
- ½" NPT thread

- ◆ **FDK-083G4332**
- ◆ **FDK-083G4331**

For DN 2...10 (1/12"...3/8") sensor
2 PVDF pipe connections (Max. 70 °C,
PN 8 bar/max 158 °F, 116 PSI), 1 grounding
ring¹⁾, 1 earthing wire, 3 PTFE gaskets, 6 pcs.
M4 x 12 and 6 pcs. M4 x 20 screws

- ½"G, ISO 7-1 tapered thread PVDF incl. grounding ring Hastelloy C22/2.4602
- ½" NPT thread PVDF incl. grounding ring Hastelloy C22/2.4602

◆ **A5E01018395**◆ **A5E01018400****EPDM gaskets**

Material: EPDM; each set includes:
2 EPDM gaskets, 1 earthing wire, 1 M6 screw,
1 nut, 1 washer, 1 bolt earthing plate

- DN 2 ... 10 (1/12" ... 3/8")
- DN 15 (½")
- DN 25 (1")

- ◆ **FDK-083G3116**
- ◆ **FDK-083G3117**
- ◆ **FDK-083G3119**

- DN 40 (1½")
- DN 50 (2")
- DN 65 (2½")

- ◆ **FDK-083G3121**
- ◆ **FDK-083G3122**
- ◆ **FDK-083G3123**

- DN 80 (3")
- DN 100 (4")

- ◆ **FDK-083G3124**
- ◆ **FDK-083G3125**

PTFE gaskets

Material: PTFE; each set includes:
2 gaskets, 2 earthing wires, 3 M6 screws
(DN 2 ... DN 10: 12 pcs M4 x 14)

- DN 2 ... 10 (1/12" ... 3/8")
- DN 15 (½")
- DN 25 (1")

- ◆ **FDK-083G0156^{F)}**
- ◆ **FDK-083G0157^{F)}**
- ◆ **FDK-083G0159^{F)}**

- DN 40 (1½")
- DN 50 (2")
- DN 65 (2½")

- ◆ **FDK-083G0161^{F)}**
- ◆ **FDK-083G0162^{F)}**
- ◆ **FDK-083G0163^{F)}**

- DN 80 (3")
- DN 100 (4")

◆ **FDK-083G0164^{F)}**
◆ **FDK-083G0165^{F)}****Graphite gaskets**

Material: Graphite; conductive,
each set includes: 2 gaskets (conductive (can
also be used as grounding ring))

- DN 2 ... 10 (1/12" ... 3/8")
- DN 15 (½")
- DN 25 (1")

- ◆ **FDK-083G0116**
- ◆ **FDK-083G0117**
- ◆ **FDK-083G0119**

- DN 40 (1½")
- DN 50 (2")
- DN 65 (2½")

- ◆ **FDK-083G0121**
- ◆ **FDK-083G0122**
- ◆ **FDK-083G0123**

- DN 80 (3")
- DN 100 (4")

◆ **FDK-083G0124**
◆ **FDK-083G0125****Accessories**

Order No.

for MAG 1100 sensor**Grounding ring SS**

Material: AISI 316/1.4436;
each set includes: 1 grounding ring¹⁾, 3 PTFE
gaskets, 1 earth wire, 1 M6 screw

- DN 2 ... 10 (1/12" ... 3/8")
- DN 15 (½")
- DN 25 (1")

◆ **FDK-083G0686**
◆ **FDK-083G0687**
◆ **FDK-083G0689**

- DN 40 (1½")
- DN 50 (2")
- DN 65 (2½")

◆ **FDK-083G0691**
◆ **FDK-083G0692**
◆ **FDK-083G0693**

- DN 80 (3")
- DN 100 (4")

◆ **FDK-083G0694**
◆ **FDK-083G0695****Grounding ring (Hastelloy C)**

Material: Hastelloy C22/2.4602;
each set includes:
1 grounding ring¹⁾, 3 PTFE gaskets, 1 earth
wire, 1 M6 screw

- DN 2 ... 10 (1/12" ... 3/8")
- DN 15 (½")
- DN 25 (1")

◆ **FDK-083G3256**
◆ **FDK-083G3257**
◆ **FDK-083G3259**

- DN 40 (1½")
- DN 50 (2")
- DN 65 (2½")

◆ **FDK-083G3261**
◆ **FDK-083G3262**
◆ **FDK-083G3263**

- DN 80 (3")
- DN 100 (4")

◆ **FDK-083G3264**
◆ **FDK-083G3265****Grounding ring (Tantalum)**

Material: Tantalum; each set includes:
1 grounding ring¹⁾, 3 PTFE gaskets, 1 earth
wire, 1 M6 screw

- DN 2 ... 10 (1/12" ... 3/8")
- DN 15 (½")
- DN 25 (1")

◆ **A5E01181599^{F)}**
◆ **A5E01181606^{F)}**
◆ **A5E01181610^{F)}**

- DN 40 (1½")
- DN 50 (2")
- DN 65 (2½")

◆ **A5E01181613^{F)}**
◆ **A5E01181615^{F)}**
◆ **A5E01181616^{F)}**

- DN 80 (3")
- DN 100 (4")

◆ **A5E01181619^{F)}**
◆ **A5E01181622^{F)}****Studs and nuts**

for DN 100 PN 25/40, 8 M20 studs,
16 M20 nuts

Material: AISI 304/1.4305

- DN 100 (4")

◆ **FDK-083G0226**¹⁾ Thickness of grounding ring is 2 mm (0.08 inch)

◆ Short lead time (details in PMD)

F) Subject to export regulations AL: 91999, ECCN: N.