Selec	ction and ordering data		Order No.						
SITR	ANS P280 WirelessHART		7MP1120-						0
-	sure transmitter								
	uired battery not included with ery, see accessories)								
Meas	suring cell filling								Г
Dry n	neasuring cell			0					
Meas	suring span								
_	ge pressure 2 bar g (0 29 psi g)				0				
	10 bar g (0 29 psi g)				E				
	50 bar g (0 725 psi g)				F				
	200 bar g (0 2900 psi g) 100 bar g (0 5800 psi g)				G H				
	lute pressure			ľ	•				
	2 bar a (0 29 psi a)			ı	VI				
	10 bar a (0 145 psi a)				N				
	50 bar a (0 725 psi a) 200 bar a (0 2900 psi a)				P 2				
	100 bar a (0 5800 psi a)			ı	2				
Wette	ed parts								
Cera	mic				K				
Disp	•								
	al display, visible					1			
	osure								
	ast aluminum					1			
	ess connection								
½-14	is per EN 837-1 NPT						0 1		
Expl	osion protection								
Witho	put							Α	
Ante	nna								
Varia	ble, attached to device							A	١
	her designs		Order code						
spec	se add "-Z" to Order No. and ify Order code(s) and plain text.								
max.	suring point number (TAG Nr.) 16 digits entered in plain text		Y15						
	suring point message		Y16						
max. text:	27 characters entered in plain Y16:								
	essories								
	ım battery for SITRANS 0/P280		7MP1990-0A	AO	0				
Mour	nting bracket, steel		7MF4997-1A0)					
Mour	nting bracket, stainless steel		7MF4997-1A	J					
Cove	r, die-cast aluminum, without ow		7MF4997-1BE	3					
Cove dow	r, die-cast aluminum, with win-		7MF4997-1BE	Ε					
IE/WS	SN-PA LINK		see Sec. 9						
HAR	T modem with RS232 interface		7MF4997-1DA	4					
HAR	Γ modem with USB interface		7MF4997-1DE	3					
SIMA	TIC PDM		see Sec. 9						
► Av	ailable ex stock				-				