

Selection and Ordering data

Order No.

Water traps

for pressure gauges and pressure transmitters, max. working temperature 120 °C (248 °F), max. working pressure 100 bar (1450 psi) (or 300 °C (572 °F) at 80 bar (1160 psi), or 400 °C (752 °F) at 63 bar (914 psi)), weight 0.7 kg

Water trap B to DIN 16282MaterialMat. No.

P235GH

1.0345

M56340-A0043

X 6 CrNiMoTi 17 12 2 1.4571/316Ti

M56340-A0061**Water trap D to DIN 16282**MaterialMat. No.

P235GH

1.0345

M56340-A0045

X 6 CrNiMoTi 17 12 2 1.4571/316Ti

M56340-A0063