Supply commitment for spare motors and repair parts following delivery of the motor	Fan cover No. 7.40, 1LA7 163–4AA60, factory number J783298901018
 For up to 5 years, in the event of total motor failure, Siemens will supply a comparable motor with regard to the mounting 	 For bearing types, see Catalog D 81.1 part 0 "Introduction".
dimensions and functions (the type series may vary).	 Repair parts for 1MJ6, 1MJ7, 1MJ8, 1MJ1, 1ME8, 1ML8, 1LG8 motors and smoke-extraction motors are available on request.
 Repair parts will be supplied for up to 5 years. For up to 10 years, Siemens will provide information and will, 	 For standard components, a supply commitment does not apply.

Support – Hotline

In Germany

if necessary, supply documentation for repair parts.
When repair parts are ordered, the following details must be provided:

provided:
- Designation and part number
- Order No. and factory number of the motor

Spare motors and repair parts

Tel.: 0180/5050448

National telephone numbers can be found on the Internet page: http://www.siemens.com/automation/service&support

Example for ordering a fan cover 1LA7, frame size 160 M, 4-pole: